	Type	Ref#	Hits	Search Text	
1	IS&R	S1	7	(("6370021") or ("d492863") or ("d482900") or ("20050275322") or ("20010054619") or ("6523716") or ("6470809")).PN.	
2	IS&R	S2	15	(("d451301") or ("6086173") or ("6012788") or ("5913582") or ("d402824") or ("d401774") or ("5806943") or ("d389664") or ("5697686") or ("d365223") or ("d339933") or ("d330294") or ("5087010") or ("d296851") or ("d257705")).PN.	
3	IS&R	S 3	2	(("5437235") or ("5927213")).PN.	
4	BRS	S4	2142	motor and (brake or braking) near5 power near5 supply	
5	BRS	S 5	1106	motor and (brake or braking) near3 power near3 supply	
6	BRS	S 6	2207	motor and (brake or braking) near5 power near5 supply	
7	IS&R	S 7	897	(318/370,362,377).CCLS.	

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; USOCR; EPO; JPO	2006/04/19 09:50		
2	US-PGPUB; USPAT; USOCR; EPO; JPO	2006/04/19 10:25		
3	US-PGPUB; USPAT; USOCR; EPO; JPO	2006/04/19 11:11		
4	US-PGPUB; USPAT; USOCR; EPO; JPO	2006/09/25 12:07		
5	US-PGPUB; USPAT; USOCR; EPO; JPO	2006/04/19 16:10		
6	US-PGPUB; USPAT; USOCR; EPO; JPO	2006/09/25 12:07		
7	US-PGPUB; USPAT; USOCR; EPO; JPO	2006/09/25 12:07		